

Sewer CCTV Inspection Report / Inspection:

Survey Date: 2017/2/17	Type of Survey: Circular	Year Commissioned:	Sewer GIS-ID: C611.1	Operator: O.BASSAK	Team Supervisor:
Start Time: 9:38:47	Weather: Dry	Camera: WI-CAM	Full Segment CCTV: Yes	Cleaned: No Pre-Cleaning	WRC Certified: 001

Road: Place: Location Details: Location Code:	JAVAHERI KHOMEIN	Project Reference No:	US MH GIS-ID: DS MH GIS-ID: SIP Length: CCTV Length:	C611.1 C971 27.8 26.72 (m)
--	-----------------------------	-----------------------	---	---

Grease Found (N/M/H): Direction of Survey: Water Level (US): Water Level (DS):	Downstream	Purpose: Pipe Size (mm): Pipe Material:	Resurvey 250 Polyethylene
---	-------------------	---	--

Comment:

Position	Code	Observation	Video	Photo	Grade
Depth: 470 (m) / Cover level:					
0.65	AMH	Manhole	00:00:04	0.jpg	0
2.34	JOM	Joint Offset Me	00:00:22	1.jpg	0
8.5	JOM	Joint Offset Me	00:01:21	2.jpg	0
14.56	JOM	Joint Offset Me	00:02:03	3.jpg	0
20.6	JAM	Joint Angular M	00:02:49	4.jpg	0
26.72	AMH	Manhole	00:04:03	5.jpg	0

Manhole and Sewer Report / Inspection:

Survey Date: 2017/2/17	Type of Survey: Circular	Weather: Dry	Manhole GIS-ID: C611.1	Operator: O.BASSAK	Team Supervisor:
Start Time: 9:38:47	Yr. Commission:	Camera: WI-CAM	WRC Certified: Yes		Cleaned: No Pre-Cleaning

Road: Place: Loc. Details: Location Code:	JAVAHERI KHOMEIN	Material: Shape: Project Ref No:	Polyethylene Circular	Pipe Size (mm): Material: Shape:	250 Polyethylene Circular
--	-----------------------------	--	----------------------------------	--	--

Cover Good Condition:	SIP Length:	27.8
Frame Good Condition:	CCTV Length:	
Water Level (US):		
Water Level (DS):		

Remarks:

No.	OP	Pos	Observation	Photo Number	Grade	Remark	Position
25	AMH	0.65	محفظه ی آدم رو	0.jpg	0		○
26	JOM	2.34	محل اتصال افست متوسط	1.jpg	0		○
27	JOM	8.5	محل اتصال افست متوسط	2.jpg	0		○
28	JOM	14.56	محل اتصال افست متوسط	3.jpg	0		○
29	JAM	20.6	محل اتصال؟؟زاویه مشترک	4.jpg	0		○
30	AMH	26.72	محفظه ی آدم رو	5.jpg	0		○

Place: KHOMEIN	Road: JAVAHERI	Date: 2017/2/17	Camera: WI-CAM	Operator: O.BASSAK
--------------------------	--------------------------	---------------------------	--------------------------	------------------------------



Photo : 0.jpg
0.65 m, Manhole # 1



Photo : 1.jpg
2.34 m, Joint Offset Medium # 2



Photo : 2.jpg
8.5 m, Joint Offset Medium # 3



Photo : 3.jpg
14.56 m, Joint Offset Medium # 4

Place: KHOMEIN	Road: JAVAHERI	Date: 2017/2/17	Camera: WI-CAM	Operator: O.BASSAK
--------------------------	--------------------------	---------------------------	--------------------------	------------------------------



Photo : 4.jpg
20.6 m, Joint Angular Medium # 5



Photo : 5.jpg
26.72 m, Manhole # 6

Place: KHOMEIN	Road: JAVAHERI	Date: 2017/2/17	Camera: WI-CAM	Operator: O.BASSAK
--------------------------	--------------------------	---------------------------	--------------------------	------------------------------

Slop & IMU Data Plots

